

SS speed St speed Al speed
 20 65 200

Spindle speed

25	3.06	9.93	30.56
40	1.91	6.21	19.10
50	1.53	4.97	15.28
63	1.21	3.94	12.13
80	0.95	3.10	9.55
100	0.76	2.48	7.64
125	0.61	1.99	6.11
160	0.48	1.55	4.77
200	0.38	1.24	3.82
250	0.31	0.99	3.06
315	0.24	0.79	2.43
400	0.19	0.62	1.91
500	0.15	0.50	1.53
630	0.12	0.39	1.21
800	0.10	0.31	0.95
1000	0.08	0.25	0.76
1250	0.06	0.20	0.61
2000	0.04	0.12	0.38

